



Vector Student SE Replacement Flap Process

17 February 2021

Please follow these steps regarding the reserve flap notice for Vector Student SE containers with a DOM between May 2013 – January 2021, in the following sizes - SE 360-1 SE 360-2, SE 360-3, SE 361, SE 364 and SE 364-1.

Field Modification

Per the included instructions, this field modification is mandatory if you wish to use your SE containers prior to installing the new reserve flap at the next repack cycle.

Reserve Flap Replacement

At the next repack cycle, please replace the reserve flap with the new one provided by UPT, following the included work instructions.

Confirm Replacement

It is important that we keep an accurate record of SE's that have the new flap installed. Once the work is completed, please email a confirmation including serial numbers to VectorSE@uptvector.com.

Rigging Costs

UPT will cover the rigging costs on this work up to a total of \$35 per SE container if needed. Please send an invoice to VectorSE@uptvector.com, detailing serial numbers and your banking details on the invoice. Alternatively, we can credit your account at UPT for use on future purchases – please note 'credit my UPT account' on the invoice if you wish to do this.

Please note, both field modification and reserve flap replacement must be completed by an FAA Master Rigger, or foreign equivalent.

We thank you for your patience and understanding in this matter.

SALES DEPARTMENT

1645 LEXINGTON AVENUE ♦ DELAND FL 32724-2106 ♦ TELEPHONE +1 386 736 7589 ♦ FAX +1 386 734 7577
WWW.UPTVECTOR.COM